chromatography
















DOC: 03-925110-03

DESC: 3800GC EFC 1079 TYPE III

PAGE: 1 of 3

## **EFC MODULE III SUB-ASSEMBLY**



PREPARED BY: HOWIE PLITSCH


REVISED BY: AJB

CONTROL: INDUSTRIAL ENGINEERING | REV. DATE: 2/4/98

**SHOWN** 

REV

3



chromatography

CHG HISTORY











DOC: 03-925110-03

DESC: 3800GC EFC 1079 TYPE III

PAGE: 3 of 3




MANIFOLD ASSY. **GOTO PAGE 2 FOR INSTALLATION** 

## NOTES: (UNLESS OTHERWISE SPECIFIED)

1. SEE O-RING PRE-ASSEMBLY INSPECTION PROCEDURE.

## **OPERATION NOTES**

- 2. AFTER CLEANING O-RINGS AND MANIFOLD MATING SURFACE, SET O-RINGS IN PLACE WITH TWEEZERS (DO NOT TOUCH O-RINGS).
- 3. FIRMLY SEAT O-RINGS IN THE MANIFOLD BLOCK.
- 4. INSPECT SEATING OF O-RINGS, IF NECESSARY PRESS TO SEAT USING TWEEZERS.
- 5. AFTER O-RING PLACEMENT "DUST-OFF" AGAIN.



**REV** 

3